Applied Force 100
108 106 108 102

Dependence of device resistance on angle between magnetization and direction of current 1.00 0.90 0.80 Normalized Delta R 0.70 0.60 0.50 0.40 0.30 0.20 0.10 0.00 15.00 30.00 45.00 60.00 75.00 90.00 Relative Angle (Theta)

FIG. 1

1, 2

(PRIOR ART)

FIG. 2




FIG. 4




FIG. 3




FIG. 5




FIG. 6




FIG. 7

